




18	1	Resistor	Stackpole Electronics	RMCF 1/16S 0 R
17	1	Resistor	Yageo	RC0402JR-07510RL
16	1	Resistor	Stackpole Electronics	RMCF 1/16S 4.7K 5% R
15	9	Resistor	Stackpole Electronics	RMCF 1/16S 10K 5% R
14	1	Resistor	Stackpole Electronics	RMCF 1/16S 1M 5% R
13	2	Ceramic Capacitor	Murata Electronics	GRM1555C1H180JZ01D
12	2	Ceramic Capacitor	Murata Electronics	GRM1555C1H470JZ01D
11	5	Ceramic Capacitor	Taiyo Yuden	EMK105BJ104KV-F
10	3	Ceramic Capacitor	TDK Corporation	C1005X5R1C334K
9	1	Diode	Comchip Technology	BAS70-G
8	1	Header	Sullins	PBC07DAAN
7	3	Socket	Samtec Inc.	QSH-030-01-L-D-A
6	1	LED	Avago Technologies	HSMY-C170
5	1	Tactile Switch	Omron	B3S-1002P
4	1	ZIF Socket	Enplas	FPQ-64-0.5-06
3	1	MCU Reset IC	STMicroelectronics	STM6315RDW13F
2	1	Crystal	NDK	NX5032GA-25.000000MHZ
1	1	PCB	Freescaler Semi	CDC2215

ITEM	QTY	NAME	MATERIAL	DESCRIPTION	
Parts List					
FILE NAME		LFMAJ04EE2M.dwg	 NXP Semiconductors 28125 Cabot Drive, Suite 100 Novi, Michigan 48377 LQFP Debug Board MPC5604 64 Pin		
CONTRACT NO		—			
DRAWN		09/01/2011 CJW			
CHECK					
APPR.					
ISSUED					
		SIZE	FSCM NO	DWG NO	REV
		B	—	LFMAJ04EE2M	
NOTE: DIMENSIONS ARE IN MILLIMETERS DO NOT SCALE DRAWING		SCALE	1:1	WEIGHT	SHEET 1 of 2